




You will need:



Solder



2 x 1/4" heat shrink tubing  
Fastenal P/N 0714595

**Tools**




Utility Knife




Soldering Iron




Hot Air Pistol




**Step 1** - Determine where the damage is and make a clean cut through the wire.




**Step 2** - Place a *heat shrink tube* over one side of the wire and the other tube over the other wire.




**Step 3** - Strip 1" of the outer insulation from both cables.




**Step 4** - Separate the *braided sheath wire* from the *inner layer of insulation*.




**Step 5** - Shorten *inner conductor wire* to 1/2".



**Step 6** - Push the *inner conductor wires* into each other and apply enough solder to secure them.




**Step 7** - Slide the *heat shrink tube* over the connections and shrink it with a *hot air pistol*. Do not use a naked flame.



IT IS EXTREMELY IMPORTANT THAT NO INNER CONDUCTOR WIRES ARE EXPOSED OUTSIDE OF HEAT SHRINK TUBE

**Step 8** - Overlap both *braided sheath wires* and solder them together.



**Step 9** - Slide the *heat shrink tube* over all the connections and shrink it with a *hot air pistol*. Do not use a naked flame.

