




FOR ELECTRICIAN



1. MAT HAS **NO** POLARITY
2. RED OR YELLOW INDICATORS ON COLD LEAD INDICATE "BEGINNING" OF MAT. WHITE INDICATORS SIGNIFY "END" OF MAT
3. COLD LEAD IS 13" AT "BEGINNING" OF MAT, 26" AT "END" OF MAT (20' & 40' LEADS ON 3' WIDE MATS)
4. ENSURE THAT ALL COLD LEADS PRESENT IN THERMOSTAT BOX ARE THE SAME DIAMETER
5. **DO NOT** SHORTEN MAT

FROM POWER SOURCE 120V & 240V



ENSURE THE SYSTEM IS GROUNDED